

Urgent Field Safety Notice

CyberKnife® System Collimator Housing Retention Issue

May 28, 2026

Issue Summary

Accuray Incorporated (Accuray) identified a potential issue during CyberKnife® collimator exchange. In certain cases, during a housing exchange operation, a collimator housing may not fully latch or release. This event triggers a system interlock while over the Xchange® table that prevents motion from the operator console. In this state, the collimator housing may fall from the CyberKnife robot while over the Xchange table. In normal use, patients should be removed from the treatment room following this system interlock. While motion is prevented from the operator console, users are capable of initiating robot motion using the in-room pendant. This motion increases the likelihood of the collimator housing falling. The collimator housing is a suspended mass that may weigh up to 49 kg. This suspended mass may fall and cause injuries. The potential harm is serious injury. No injuries have been reported.

Please ensure that all necessary personnel in your facility are made aware of this notification and the appropriate steps to assess and correct the matter.

Reason for Urgent Field Safety Notice

Accuray received reports of personnel entering the treatment room after the system interlock and using the in-room control pendant to initiate treatment robot motion, which can allow an incompletely latched collimator housing to release and fall. If this condition occurs, do not use the in-room control pendant to restore motion. Contact Accuray Service (or your authorized service provider) for assistance.



Figure: CyberKnife® System collimator housing location.

Accuray Service personnel, including distributor service personnel, are aware of this issue. Although using third-party service providers will void your system warranty, if your CyberKnife System is serviced by a third-party provider, please ensure they are also informed.

Affected Product

This issue affects all CyberKnife Treatment Delivery Systems equipped with the Xchange Robotic Collimator Changer.

The CyberKnife Treatment Delivery System is indicated for image-guided stereotactic radiosurgery and precision radiotherapy for lesions, tumors, and conditions anywhere in the body when radiation treatment is indicated. The table below shows a list of UDI-DI impacted systems.

UDI-DI	
M6580531010	811376030436
00811376030443	M6580532010
00811376030450	M6580533010
00811376030467	M6580534010
00811376030498	M65810476410
M6581055810	00811376030023
00811376030016	M65806600000
00811376030368	00811376030429
M6580325000	M6580330000

Safety Instructions

This condition may occur during housing drop off or pick up while the collimator housing is positioned over the Xchange table. The system will interlock, stop motion, and display a message at the operator console to contact service. If an interlock occurs: (1) remove the patient from the treatment room before troubleshooting, (2) do not initiate treatment robot motion from the in-room control pendant, and (3) contact Accuray Service to safely release the collimator housing.

Product Correction

Accuray is committed to providing our customers and their patients with products that deliver safe radiation treatments. Accuray will provide a product correction that limits initiating motion from the in-room control pendant when this condition is detected.

Contact Information

For questions about this Urgent Field Safety Notice, please contact Accuray Customer Support by phone or email, using the Service Request form available at <http://www.accuray.com/service-requests>.

The notice has been sent to the appropriate Regulatory Agencies.

Sincerely,

Daniel Biank
Vice President, Regulatory & Government Affairs
Accuray Regulatory and Quality
Accuray Incorporated
1209 Deming Way
Madison, WI 53717

Accuray Regulatory and Quality
Accuray Incorporated
1209 Deming Way
Madison, WI 53717

Urgent Field Safety Notice Acknowledgement Form

I acknowledge that I have received the following document from Accuray:

Urgent Field Safety Notice concerning the CyberKnife® System Collimator Exchange Retention Issue

I confirm that I understand the content of this Urgent Field Safety Notice dated May 28, 2026 and have distributed the information to all applicable members of my staff.

Hospital Name (no abbreviations please): _____

System Serial Number(s): _____

Signature: _____

Name (print): _____

Date: _____

Please keep this Urgent Field Safety Notice document with your User Manual and forward a copy to:

Email to: FANotification@accuray.com

Or send hard copy to:

FA Notification (Product Surveillance)
Accuray Incorporated
1209 Deming Way
Madison, WI 53717