CUSTOMER INFORMATION

URGENT FIELD SAFETY NOTICE Field Safety Corrective Action

Antistreptolysin O FS Cat. No. 1 7012...

Possible deviating results of individual Antistreptolysin O FS lot

Date Nov 10, 2017

Product Antistreptolysin O FS Cat. No. 1 7012...

Lot: The following lot is affected.

24286, expiry date 2019-06

Explanation A deviating reactivity of the above mentioned Antistreptolysin O FS lot,

compared to former lots, has been detected.

Impact on patient results

Patient values are found falsley high.

Measures New calibrator values will be determined for the above mentioned lot. We will

inform you about the new calibrator values in the course of next week. You can again use the above mentioned lot as soon as the new calibrator values are

available. Until then, the above mentioned lot must not be used.

Please discuss with the head of laboratory if patient values determined with

above mentioned lot should be repeated.

Please inform all users immediately.



Page 1/2

CUSTOMER INFORMATION

DiaSys has announced the urgent field safety notice to the relevant authorities of the European Union. Customers outside the EU are asked to handle necessary announcements to authorities in their countries.

Under current regulations we are obliged to provide a complete chain of evidence of all corrective measures for our products. For this reason, we would like to ask you to fill in and sign the attached confirmation that you have received and communicated this information to all concerned customers. Please send it back to us by fax or as scan until **Nov 24, 2017.**

Please accept our sincere apologies for the inconvenience caused. In case you have any questions, please do not hesitate to contact us.

Kind regards,

Dr. Sebastian Runkel Strategic Product Management



Page 2/2