# STERIS

### **URGENT MEDICAL DEVICE FIELD SAFETY CORRECTIVE ACTION**

### Hookup Accessories used with MEDIVATORS ADVANTAGE PLUS, ADVANTAGE PLUS Pass Thru, and ISA Automated Endoscope Reprocessors

November 20, 2023

#### ATTN: GI DIRECTOR OR STERILE PROCESSING DEPARTMENT

Dear Valued STERIS Customer:

STERIS is voluntarily conducting a recall for hookup accessories used with the MEDIVATORS<sup>™</sup> ADVANTAGE PLUS<sup>™</sup>, ADVANTAGE PLUS Pass Thru, and ISA Automated Endoscope Reprocessors **distributed between July 21** – **November 13, 2023**. Our records indicate that your facility purchased one or more of the hookups impacted by this recall. Please reference Attachment A to this letter for the full list of affected models and UDIs.

**Description of the product** – Hookups are intended to provide the interface between an Automated Endoscope Reprocessor (AER) and endoscopes, which allow perfusion of liquids dispensed by the AER to contact and high-level disinfect the channels of flexible endoscopes.

**Description of the problem** – Through receipt of Customer complaints, it has been determined that the identification label on affected hookups could become illegible over time due to the label's ink coming off. If the information on the hookup label were to become illegible, this may result in an inconvenience to users, or in some cases where a user facility does not have a backup hookup, potentially prevent the user from being able to effectively identify the hookup (i.e., delineate one affected hookup from another). This may result in the user electing to not reprocess certain endoscopes, which could result in postponement of patient procedures.

STERIS Action – STERIS will provide either a replacement hookup or replacement label for all affected hookups.

<u>User Action</u> – Please ensure the following steps are completed:

- 1. Please inspect your on-hand inventory for product affected by this recall. You should not attempt to use a hookup that cannot be effectively identified.
- Please complete the Medical Device Recall Response Form included with this letter, and return the completed Response Form via email to: Regulatory\_Compliance@STERIS.com or via fax to 440-392-8963. IMPORTANT NOTE: No replacement hookup(s) or label(s) will be provided until a completed Response Form is received.

We apologize for any inconvenience this matter may cause, and as always, STERIS is dedicated to supporting our products and valued Customers. If you have questions regarding this matter, please contact Regulatory\_Compliance@STERIS.com.

Sincerely,

michellodavan

Michelle LaVan Lead, Quality & Regulatory Compliance Specialist STERIS



### MEDICAL DEVICE RECALL RESPONSE FORM

## **RESPONSE IS REQUIRED**

City, State, Zip/Postal Code: \_\_\_\_\_

# Hookup Accessories used with ADVANTAGE PLUS, ADVANTAGE PLUS Pass Thru, and ISA Automated Endoscope Reprocessors

<u>IMPORTANT</u>: Replacement hookup(s) or replacement label(s) will be provided based on affected product shipped to your facility. Please fill out this form in its entirety and return to STERIS to initiate the replacement process.

Printed Name and Title

\*Signature and Date

\*By signing this Response Form, you are confirming that your facility will not attempt to use a hookup that cannot be effectively identified.

Please fill out in entirety, scan, and return via email to Regulatory\_Compliance@STERIS.com or via fax to 440-392-8963.

Model #	Model Description	UDI
2-8-001	HU ZERO CHANNEL NO LT	00677964068515
2-8-010	ASSY, HOOK-UP, OLYMPUS	00677964068478
2-8-014	HOOKUP, OPTIM LT	00677964095177
2-8-030	ASSY, HOOKUP, PENTAX-0K	00677964071348
2-8-040	ASSY, HKUP STORZ 0K	00677964072284
2-8-070	ASSY, HU VISION SCIENCE	00677964094637
2-8-112	ASSY, HOOKUP OLMPUS 1K	00677964071300
2-8-120	ASSY, HOOKUP FUJI 1K	00677964102080
2-8-210	ASSY, HOOK-UP OLYMPUS 2K	00677964068485
2-8-213	ASSY, HOOKUP, OLYMPUS-2K	00677964070648
2-8-218	ASSY HOOKUP OLY 2K	00677964072369
2-8-236	ASSY, HOOKUP FUJINON 2K	00677964072376
2-8-244	ASSY, HOOKUP, STORZ 2K	00677964071836
2-8-245	ASSY, HOOK-UP, STORZ 2K	00677964071195
2-8-246	ASSY, HKUP, PENTAX-2K	00677964084058
2-8-260	ASSY, HOOK-UP WOLF 2-K	00677964105951
2-8-280	ASSY HOOKUP	00677964073069
2-8-312	ASSY, HOOK-UP OLYMPUS-3K	00677964074400
2-8-330	ASSY, HOOK-UP, PENTAX-3K	00677964073816
2-8-332	ASSEMBLY, HOOK-UP, PENTAX	00677964091483
2-8-334	ASSEMBLY, HOOK-UP, PENTAX	00677964073830
2-8-335	ASSY, HOOKUP, OLYMPUS, 3K	00677964071263
2-8-336	ASSY,HKUP FUJI 70 BRONC	00677964091506
2-8-338	ASSY, HU, FUJI BRONCH U/S	00677964074141
2-8-421	ASSY, HOOKUP, FUJIFILM	00677964071270
2-8-428	ASSY, ED-580XX	00677964104923
2-8-431	ASSY, HOOKUP, PENTAX	00677964071706
2-8-432	ASSY, HOOK-UP, PENTAX	00677964072239
2-8-460	HOOKUP, ASSY WOLF 4K	00677964092756
2-8-511	ASSY, HOOK-UP, OLY	00677964066726
2-8-513	ASSY HOOKUP OLY 4K ESOPHA	00677964102394
2-8-522	ASSY, FUJINON 4K-JET	40677964025387
2-8-523	ASSY, HKUP, FUJI 4K SER 5	00677964074158
2-8-526	ASSY, HOOKUP FUJI 4K+JET	00677964071904
2-8-527	ASSY, FUJI 700 NO FWJ	00677964111648
2-8-528	HOOK, EI-580BT	40677964025394
2-8-534	ASSY, HOOK-UP, PEN-4K+JET	00677964073632
2-8-537	ASSY, HKUP, PTX90 4K+JET	00677964068492
2-8-539	HOOK, PTX I20 FWJ	40677964039827
2-8-540	ASSY-HOOK-UP,STORZ,5K	00677964091223
2-8-611	ASSY, HOOK-UP, OLY	00677964066719
2-8-612	ASSY, HOOKUP, PENTAX	00677964073571
2-8-614	ASM HU OLY TGF-UC180J	00677964101984
2-8-617	ASSY, HKUP, OLY 2 BIOPSY	00677964073427
2-8-623	ASSY,HKUP,FUJI-5 4K+JET	00677964091476
2-8-625	ASSY, HOOKUP, EG-580UT	00677964077678
2-8-626	ASSY, HOOKUP, EG-580UR	00677964077685
2-8-627	ASSY, HKUP, FUJI 700 SER	00677964083006
2-8-634	ASSY, HOOKUP PENTAX DUAL	00677964074189
2-8-639	HOOK, EG3X-J10	40677964006560
2-8-640	ASSY,HOOK-UP STORZ 6K	00677964074417

### Attachment A – List of affected Hookup models and UDIs

Model #	Model Description	UDI
2-8-711	ASSY, HOOKUP, OLYMPUS 5K	00677964070662
2-8-718	ASSY, HOOKUP, OLY 160/180	00677964070655
2-8-740	ASSY, HOOK-UP, STORZ	00677964102479
2-8-811	ASSY HKUP OLY-ECHO+LIFT	00677964070624
2-8-901	KIT TEE/TOE/RUS HU ADV+	00677964046926
5-8-010	ASSY, HOOKUP DBL LT	00677964071874
5-8-030	ASSY, HOOKUP	00677964094644
5-8-040	ASSY HOOKUP STORZ 0K DBL	00677964072772
5-8-050	ASSY, HOOKUP, DILATOR	00677964072963
5-8-112	HOOKUP 2-SCOPE 1-K	00677964072307
5-8-190	HOOK DBL, IS, ION	40677964025493
5-8-210	ASSY, HOOKUP	00677964080333
5-8-245	HOOKUP KARLSTORZ-2K	00677964102493
2-8-001HAN	HU ZERO CHANNEL NO LT	00677964064739
2-8-002HAN	ADVANTAGE TEST BLOCK	00677964046568
2-8-010HAN	ASSEMBLY, HOOK-UP,OLYMPUS	00677964001802
2-8-030HAN	ASSY,HOOKUP,PENTAX-OK	00677964037399
2-8-112HAN	ASSY, HOOK-UP OLYMPUS 1K	00677964001819
2-8-160HAN	ASSY, ADV HOOKUP, WOLF	00677964037443
2-8-210HAN	ASSY, HOOK-UP OLYMPUS 2K	00677964001826
2-8-213HAN	ASSY, HOOKUP, OLYMPUS-2K	00677964001871
2-8-218HAN	ASSY HOOKUP OLY 2K	00677964061707
2-8-245HAN	ASSY, HOOKUP, STORZ-2K	00677964037511
2-8-330HAN	ASSY, HOOK-UP, PENTAX-3K	00677964001970
2-8-334HAN	ASSEMBLY, HOOK-UP, PENTAX	00677964001970
2-8-335HAN	ASSY,HOOKUP,OLYMPUS	00677964037634
2-8-336HAN	ASSY,HKUP FUJI 70 BRONC	00677964045387
2-8-338HAN	ASSY, HU, FUJI BRONCH U/S	00677964053443
2-8-421HAN	ASSY, HOOKUP, FUJINON	00677964037658
2-8-428CAS	HOOK, CAS, ED-580XX	40677964024663
2-8-428HAN	HOOK, HAN, ED-580XX	40677964024603
2-8-431CAS	ASSY, CASSETTE, PENTAX	00677964002045
2-8-431HAN	ASSY, HOOK-UP, PENTAX	
2-8-511HAN	ASSY, HOOK-UP, OLY	00677964002052
2-8-526HAN	ASSY, HOOKUP FUJI 4K+JET	00677964002144 00677964053764
2-8-536HAN	HOOKUP,PENTAX,70ULT, 5K	00677964044168
2-8-537CAS	ASSY,CASS,PTX 90 4K+JET	00677964037801
2-8-537HAN	ASSY HKUP,PTX90 4K+JET	
2-8-611HAN	ASST IIKOL, I IX70 4K (JET ASSY, HOOK-UP, OLY	00677964037818
2-8-626CAS	ASSY, CASS, FUJINON 580UR	00677964002236
2-8-627HAN	ASSY, HAN, FUJI 700 SER	00677964077661
2-8-634CAS	ASSY,CASS PENTAX DUAL CH	00677964089701
2-8-634HAN	ASSY,HOOKUP PENTAX DUAL CH	00677964054815
2-8-640HAN	ASSY, HOOK-UP STORZ 6K	00677964054808
2-8-711HAN	ASSY, HOOKUP, OLYMPUS-5K	00677964087097
2-8-718HAN	ASSY, HOOKUP, OLY MPUS-5K ASSY, HOOK-UP, OLY 160/180	00677964037924
2-8-811HAN	ASSY HKUP OLY-ECHO W/LIFT	00677964064777
2-8-902H	HU BLOCK ULTRASOUND PROBE	00677964053542
5-8-030HAN	ASSY, HOOKUP	00677964061509
5-8-050HAN	ASSY, HOOKUP ASSY, HOOKUP, DILATOR	00677964046681
		00677964040306
5-8-112HAN	ASSY, HOOKUP 2-SCOPE 1-K	00677964051548
5-8-244HAN	ASSY, HKUP 2K DBL	00677964045165

# STERIS STERIS

### **URGENT MEDICAL DEVICE FIELD SAFETY CORRECTIVE ACTION**

### Hookup Accessories used with MEDIVATORS ADVANTAGE PLUS, ADVANTAGE PLUS Pass Thru, and ISA Automated Endoscope Reprocessors

November 20, 2023

#### **ATTN: PURCHASING DEPARTMENT**

Dear Valued STERIS Distributor:

STERIS is voluntarily conducting a recall for hookup accessories used with the MEDIVATORS<sup>™</sup> ADVANTAGE PLUS<sup>™</sup>, ADVANTAGE PLUS Pass Thru, and ISA Automated Endoscope Reprocessors **distributed between July 21** – **November 13, 2023**. Our records indicate that your facility purchased one or more of the hookups impacted by this recall. Please reference Attachment A to this letter for the full list of affected models and UDIs.

**Description of the product** – Hookups are intended to provide the interface between an Automated Endoscope Reprocessor (AER) and endoscopes, which allow perfusion of liquids dispensed by the AER to contact and high-level disinfect the channels of flexible endoscopes.

**Description of the problem** – Through receipt of Customer complaints, it has been determined that the identification label on affected hookups could become illegible over time due to the label's ink coming off. If the information on the hookup label were to become illegible, this may result in an inconvenience to users, or in some cases where a user facility does not have a backup hookup, potentially prevent the user from being able to effectively identify the hookup (i.e., delineate one affected hookup from another). This may result in the user electing to not reprocess certain endoscopes, which could result in postponement of patient procedures.

**<u>STERIS Action</u>** – STERIS will provide either a replacement hookup or replacement label for all affected hookups.

<u>User Action</u> – Please ensure the following steps are completed:

- 1. Please inspect your on-hand inventory for product affected by this recall. You should not attempt to use a hookup that cannot be effectively identified.
- Please complete the Medical Device Recall Response Form included with this letter, and return the completed Response Form via email to: Regulatory\_Compliance@STERIS.com or via fax to 440-392-8963. IMPORTANT NOTE: No replacement hookup(s) or label(s) will be provided until a completed Response Form is received.
- 3. If you have further distributed this product, please identify your Customer(s), and notify them of this field recall.

We apologize for any inconvenience this matter may cause, and as always, STERIS is dedicated to supporting our products and valued Customers. If you have questions regarding this matter, please contact Regulatory\_Compliance@STERIS.com.

Sincerely,

Michelle Lavan

Michelle LaVan Lead, Quality & Regulatory Compliance Specialist STERIS



### MEDICAL DEVICE RECALL RESPONSE FORM

## **RESPONSE IS REQUIRED**

City, State, Zip/Postal Code: \_\_\_\_\_

# Hookup Accessories used with ADVANTAGE PLUS, ADVANTAGE PLUS Pass Thru, and ISA Automated Endoscope Reprocessors

<u>IMPORTANT</u>: Replacement hookup(s) or replacement label(s) will be provided based on affected product shipped to your facility. Please fill out this form in its entirety and return to STERIS to initiate the replacement process.

Printed Name and Title

\*Signature and Date

\*By signing this Response Form, you are confirming that your facility will not attempt to use a hookup that cannot be effectively identified.

Please fill out in entirety, scan, and return via email to Regulatory\_Compliance@STERIS.com or via fax to 440-392-8963.

Model #	Model Description	UDI
2-8-001	HU ZERO CHANNEL NO LT	00677964068515
2-8-010	ASSY, HOOK-UP, OLYMPUS	00677964068478
2-8-014	HOOKUP, OPTIM LT	00677964095177
2-8-030	ASSY, HOOKUP, PENTAX-0K	00677964071348
2-8-040	ASSY, HKUP STORZ 0K	00677964072284
2-8-070	ASSY, HU VISION SCIENCE	00677964094637
2-8-112	ASSY, HOOKUP OLMPUS 1K	00677964071300
2-8-120	ASSY, HOOKUP FUJI 1K	00677964102080
2-8-210	ASSY, HOOK-UP OLYMPUS 2K	00677964068485
2-8-213	ASSY, HOOKUP, OLYMPUS-2K	00677964070648
2-8-218	ASSY HOOKUP OLY 2K	00677964072369
2-8-236	ASSY, HOOKUP FUJINON 2K	00677964072376
2-8-244	ASSY, HOOKUP, STORZ 2K	00677964071836
2-8-245	ASSY, HOOK-UP, STORZ 2K	00677964071195
2-8-246	ASSY, HKUP, PENTAX-2K	00677964084058
2-8-260	ASSY, HOOK-UP WOLF 2-K	00677964105951
2-8-280	ASSY HOOKUP	00677964073069
2-8-312	ASSY, HOOK-UP OLYMPUS-3K	00677964074400
2-8-330	ASSY, HOOK-UP, PENTAX-3K	00677964073816
2-8-332	ASSEMBLY, HOOK-UP, PENTAX	00677964091483
2-8-334	ASSEMBLY, HOOK-UP, PENTAX	00677964073830
2-8-335	ASSY, HOOKUP, OLYMPUS, 3K	00677964071263
2-8-336	ASSY,HKUP FUJI 70 BRONC	00677964091506
2-8-338	ASSY, HU, FUJI BRONCH U/S	00677964074141
2-8-421	ASSY, HOOKUP, FUJIFILM	00677964071270
2-8-428	ASSY, ED-580XX	00677964104923
2-8-431	ASSY, HOOKUP, PENTAX	00677964071706
2-8-432	ASSY, HOOK-UP, PENTAX	00677964072239
2-8-460	HOOKUP, ASSY WOLF 4K	00677964092756
2-8-511	ASSY, HOOK-UP, OLY	00677964066726
2-8-513	ASSY HOOKUP OLY 4K ESOPHA	00677964102394
2-8-522	ASSY, FUJINON 4K-JET	40677964025387
2-8-523	ASSY, HKUP, FUJI 4K SER 5	00677964074158
2-8-526	ASSY, HOOKUP FUJI 4K+JET	00677964071904
2-8-527	ASSY, FUJI 700 NO FWJ	00677964111648
2-8-528	HOOK, EI-580BT	40677964025394
2-8-534	ASSY, HOOK-UP, PEN-4K+JET	00677964073632
2-8-537	ASSY, HKUP, PTX90 4K+JET	00677964068492
2-8-539	HOOK, PTX I20 FWJ	40677964039827
2-8-540	ASSY-HOOK-UP,STORZ,5K	00677964091223
2-8-611	ASSY, HOOK-UP, OLY	00677964066719
2-8-612	ASSY, HOOKUP, PENTAX	00677964073571
2-8-614	ASM HU OLY TGF-UC180J	00677964101984
2-8-617	ASSY, HKUP, OLY 2 BIOPSY	00677964073427
2-8-623	ASSY,HKUP,FUJI-5 4K+JET	00677964091476
2-8-625	ASSY, HOOKUP, EG-580UT	00677964077678
2-8-626	ASSY, HOOKUP, EG-580UR	00677964077685
2-8-627	ASSY, HKUP, FUJI 700 SER	00677964083006
2-8-634	ASSY, HOOKUP PENTAX DUAL	00677964074189
2-8-639	HOOK, EG3X-J10	40677964006560
2-8-640	ASSY,HOOK-UP STORZ 6K	00677964074417

### Attachment A – List of affected Hookup models and UDIs

Model #	Model Description	UDI
2-8-711	ASSY, HOOKUP, OLYMPUS 5K	00677964070662
2-8-718	ASSY, HOOKUP, OLY 160/180	00677964070655
2-8-740	ASSY, HOOK-UP, STORZ	00677964102479
2-8-811	ASSY HKUP OLY-ECHO+LIFT	00677964070624
2-8-901	KIT TEE/TOE/RUS HU ADV+	00677964046926
5-8-010	ASSY, HOOKUP DBL LT	00677964071874
5-8-030	ASSY, HOOKUP	00677964094644
5-8-040	ASSY HOOKUP STORZ 0K DBL	00677964072772
5-8-050	ASSY, HOOKUP, DILATOR	00677964072963
5-8-112	HOOKUP 2-SCOPE 1-K	00677964072307
5-8-190	HOOK DBL, IS, ION	40677964025493
5-8-210	ASSY, HOOKUP	00677964080333
5-8-245	HOOKUP KARLSTORZ-2K	00677964102493
2-8-001HAN	HU ZERO CHANNEL NO LT	00677964064739
2-8-002HAN	ADVANTAGE TEST BLOCK	00677964046568
2-8-010HAN	ASSEMBLY, HOOK-UP,OLYMPUS	00677964001802
2-8-030HAN	ASSY,HOOKUP,PENTAX-OK	00677964037399
2-8-112HAN	ASSY, HOOK-UP OLYMPUS 1K	00677964001819
2-8-160HAN	ASSY, ADV HOOKUP, WOLF	00677964037443
2-8-210HAN	ASSY, HOOK-UP OLYMPUS 2K	00677964001826
2-8-213HAN	ASSY, HOOKUP, OLYMPUS-2K	00677964001871
2-8-218HAN	ASSY HOOKUP OLY 2K	00677964061707
2-8-245HAN	ASSY, HOOKUP, STORZ-2K	00677964037511
2-8-330HAN	ASSY, HOOK-UP, PENTAX-3K	00677964001970
2-8-334HAN	ASSEMBLY, HOOK-UP, PENTAX	00677964001994
2-8-335HAN	ASSY,HOOKUP,OLYMPUS	00677964037634
2-8-336HAN	ASSY,HKUP FUJI 70 BRONC	00677964045387
2-8-338HAN	ASSY, HU, FUJI BRONCH U/S	00677964053443
2-8-421HAN	ASSY, HOOKUP, FUJINON	00677964037658
2-8-428CAS	HOOK, CAS, ED-580XX	40677964024663
2-8-428HAN	HOOK, HAN, ED-580XX	40677964024670
2-8-431CAS	ASSY, CASSETTE, PENTAX	00677964002045
2-8-431HAN	ASSY, HOOK-UP, PENTAX	1
2-8-511HAN	ASSY, HOOK-UP, OLY	00677964002052
2-8-526HAN	ASSY, HOOKUP FUJI 4K+JET	00677964002144 00677964053764
2-8-536HAN	HOOKUP,PENTAX,70ULT, 5K	00677964044168
2-8-537CAS	ASSY,CASS,PTX 90 4K+JET	00677964037801
2-8-537HAN	ASSY HKUP,PTX90 4K+JET	
2-8-611HAN	ASST IIKOL, I IXJO 4K (JET ASSY, HOOK-UP, OLY	00677964037818
2-8-626CAS	ASSY, CASS, FUJINON 580UR	00677964002236
2-8-627HAN	ASSY, HAN, FUJI 700 SER	00677964077661
2-8-634CAS	ASSY, CASS PENTAX DUAL CH	00677964089701
2-8-634CAS 2-8-634HAN	ASSY, CASS PENTAX DUAL CH ASSY, HOOKUP PENTAX DUAL	00677964054815
2-8-634HAN 2-8-640HAN	ASSY, HOOK-UP STORZ 6K	00677964054808
		00677964087097
2-8-711HAN	ASSY, HOOKUP, OLYMPUS-5K	00677964037924
2-8-718HAN 2-8-811HAN	ASSY,HOOK-UP, OLY 160/180 ASSY HKUP OLY-ECHO W/LIFT	00677964064777
		00677964053542
2-8-902H	HU BLOCK ULTRASOUND PROBE	00677964061509
5-8-030HAN	ASSY, HOOKUP	00677964046681
5-8-050HAN	ASSY,HOOKUP, DILATOR	00677964040306
5-8-112HAN	ASSY, HOOKUP 2-SCOPE 1-K	00677964051548
5-8-244HAN	ASSY, HKUP 2K DBL	00677964045165