

Axis-Shield Diagnostics Ltd Luna Place, The Technology Park, Dundee, DD2 1XA, UK.



Immediate Action Required

Date Issued 09 MARCH 2020

Product

| Product Name | List Number | Lot Number | Expiration Date | UDI Number |
|-----------------|----------------|---------------|--------------------|------------|
| Alere | 2R10-01 | 902929466 | 03APR2020 | N/A |
| NT-proBNP | 2810-01 | 902929915 | 06MAY2020 | N/A |
| Alere | 04\$7901 | 10976UP00 | 03APR2020 | N/A |
| NT-proBNP | 0437901 | 10991UP00 | 06MAY2020 | N/A |
| Alere | 2R10-10 | 902929465 | 03APR2020 | N/A |
| NT-proBNP | 2110-10 | 902929899 | 05MAY2020 | N/A |
| Alere | 04\$7910 | 10975UP00 | 03APR2020 | N/A |
| NT-proBNP | 0437910 | 10989UP00 | 05MAY2020 | N/A |

Explanation

The purpose of this letter is to inform you of a product recall for the Alere NT-proBNP Calibrator and Control lot numbers listed above for use on the ARCHITECT or Alinity i systems.

All of the lots listed above demonstrate higher than expected quality control variation and / or patient sample returns when testing on the ARCHITECT and Alinity i systems.

Internal testing has confirmed this is due to an unacceptable stability drift in quality control values, when compared to the initial market release values of the calibrator lots listed.

If Calibrators and Controls with the same assigned expiry date are used together the Control values may not be elevated as the material may have similar stability drift.

Patient ImpactThis issue may generate falsely elevated patient results that may go undetected if quality
controls do not detect the shift.

Necessary Actions

Immediately discontinue use of the affected calibrator and / or control lots listed and switch to the alternate material lot(s) you have available.

Immediately destroy any remaining inventory of the affected calibrator and / or controls lots listed according to your laboratory procedures.

Immediately order replacement material(s) if you do not have unaffected material available.

Please retain this letter for your laboratory records.

New replacements lots of Alere NT-proBNP Calibrator and Controls for use on the ARCHITECT and /or Alinity i systems, should be used. These will have shortened dating.

Please take this into consideration when reordering.

Contact Information

We sincerely regret any inconvenience this may have caused your laboratory. If you, or any of the healthcare providers you serve, have any questions regarding this information, please contact your local area Customer Service.