

Boston Scientific International S.A.

ZAC Paris Nord II/Bât Emerson - 33 rue des Vanesses – 93420 Villepinte **Siège social :** Parc du Val Saint Quentin – 2 rue René Caudron 78960 Voisins le Bretonneux – France

Tel 33 (0)1 48 17 47 00 Fax 33 (0)1 48 17 47 01 www.bostonscientific.com

«Hospital_Name»

«Users_Name»- «Department» «Customer_Address» «Zip_Code» «City» - «Country_name»

Reference: 92378480-FA 29 April 2019

Urgent Field Safety Notice (for Distributor) - Medical Device Withdrawal

XenformTM Soft Tissue Repair Matrix

UpholdTM Lite with Capio SLIM Vaginal Support System

PolyformTM Synthetic Mesh

PinnacleTM LITE Pelvic Floor Repair Kit, Posterior

Dear «Users_Name»,

Boston Scientific is implementing a withdrawal of the following products indicated for transvaginal placement of pelvic organ prolapse:

- XenformTM Soft Tissue Repair Matrix
- UpholdTM LITE with Capio SLIM Vaginal Support System
- PolyformTM Synthetic Mesh
- PinnacleTM LITE Pelvic Floor Repair Kit, Posterior

On Tuesday, April 16, 2019, the United States Food and Drug Administration (FDA) ordered all manufacturers of surgical mesh for transvaginal repair of pelvic organ prolapse to stop selling products immediately and withdraw all products from the US market. FDA does not believe sufficient clinical evidence is available to assure the benefits of these devices outweigh their probable risks; for the US market this withdrawal was specific to only XenformTM Soft Tissue Repair Matrix and UpholdTM LITE with Capio SLIM Vaginal Support System

Based on this FDA decision and the global regulatory environment regarding transvaginal mesh for this indication, BSC has now made the decision to voluntarily withdraw from inventory, all products listed above from the rest of the world, which are indicated for the transvaginal repair of pelvic organ prolapse.

Clinical Recommendations

Boston Scientific recommends that patients who have had transvaginal mesh placed for the surgical repair of pelvic organ prolapse should continue with their annual, other routine check-ups, and follow-up care. There is no need to take any additional action if patients are satisfied with their surgery and are not having any complications or symptoms.



Next Steps

Following is a list of affected products in scope of this action, all batches of which are to be withdrawn. No other BSC products are impacted by this withdrawal.

Attached to this letter is a specific listing of products which we have record of shipping to your facility. Please segregate the product immediately and return it to Boston Scientific in accordance with the enclosed instructions.

AFFECTED PRODUCT LISTING

| UPN | Description | GTIN | Batch |
|-------------|---|----------------|-------------|
| M0068302410 | Xenform [™] Tissue Repair Matrix - 2cm X 7cm | 8714729775133 | All batches |
| M0068302430 | Xenform [™] Tissue Repair Matrix - 4cm X 7cm | 8714729774464 | |
| M0068302450 | Xenform [™] Tissue Repair Matrix 6cm X 10cm | 8714729773764 | |
| M0068302470 | Xenform [™] Tissue Repair Matrix 8cm x 12cm | 8714729774198 | |
| M0068318170 | Uphold™ LITE with Capio SLIM Vaginal Support System | 8714729839200 | |
| M0068402400 | Polyform TM Synthetic Mesh, 10cm x 15cm, box 1 | 08714729121305 | |
| M0068402410 | Polyform TM Synthetic Mesh, 15cm x 20cm, box 1 | 08714729767015 | |
| M0068318150 | Pinnacle™ LITE Pelvic Floor Repair Kit, Posterior | 08714729854548 | |

Further distribution or use of any remaining product affected by this action should cease immediately.

INSTRUCTIONS:

- 1- Check your Inventory for the products affected by this Field safety Notice.
- 2- Please segregate and do not distribute any of the affected products found in your inventory.
- 3- Please notify all your customers that have received affected product of this Field Safety Notice. To effectively manage this Field Safety Notice, your accounts are to communicate directly with you, not Boston Scientific. If any of your customers are distributors, please notify them that they must communicate this recall to the medical facility level.
- 4- Have all affected product returned to your facility and held in quarantine for reconciliation
- 5- Please complete the attached Verification Form, even if you do not have any product to return.
- 6- When completed, please return the Verification Form to your local Boston Scientific office for the attention of «Customer Service Fax Number» on or before 15 May 2019.
- 7- If you have products to return, please package them in an appropriate shipping box and contact «Customer Service Tel» of your local Boston Scientific office, to arrange return.



Your Competent Authority is being notified of this Field Safety Notice.

We regret any inconvenience that this action may cause, and we appreciate your understanding as we act to ensure patient safety and customer satisfaction. We are committed to continuing to offer products that meet the high-quality standards that you expect from Boston Scientific.

If you have any questions or would like assistance with this Field Safety Notice, please contact your local Sales Representative.

Yours sincerely,

Marie Pierre Barlangua Quality Department

Boston Scientific International S.A.

Attachment: Verification Form